



LF Bioenergy

LF Bioenergy LF1 LLC  
2950 N. Hardwood St.  
Suite 2200  
Dallas TX 75201  
Tax ID # 87-1230439

# Purchase Order

Date 11/6/2024  
PO # PO288  
Receive By  
Terms Net 30  
Incoterm

**Vendor**  
Nutrient Control Systems Inc.  
130 Industrial Drive  
Chambersburg PA 17201  
United States

**Ship To**  
Stauffer  
1080 County Route 55  
North Lawrence NY 12967  
United States

**Project**

## Memo

Quote #393 TBM 150's Expanded rebuild kit

Item	Quantity	Description	Rate	Amount	Tax Amt.
Maintenance Expense : Manure Thickening Spare Parts	1	1 TBM 150 Mixer Bushing with Ceramic Coating 200-007730 <b>3</b> \$1,181.69 -\$354.51 \$827.18		827.18	
Maintenance Expense : Manure Thickening Spare Parts	1	2 Jam Nut 200-100450 <b>3</b> \$248.93 -\$74.68 \$174.25		174.25	
Maintenance Expense : Manure Thickening Spare Parts	1	3 Washer 200-100514 <b>3</b> \$41.40 -\$12.42 \$28.98		28.98	
Maintenance Expense : Manure Thickening Spare Parts	1	4 O-Ring (568-169) 200-100306 <b>6</b> \$27.30 -\$8.19 \$19.11		19.11	
Maintenance Expense : Manure Thickening Spare Parts	1	5 Bearing 200-100201 <b>3</b> \$566.12 -\$169.84 \$396.28		396.28	
Maintenance Expense : Manure Thickening Spare Parts	1	6 Bearing 200-100200 <b>6</b> \$1,029.68 -\$308.91 \$720.78		720.78	
Maintenance Expense : Manure Thickening Spare Parts	1	7 HO-3 ISO VG-150 HD lube oil Sold By Liter L0764-057L <b>8</b> \$421.03 -\$126.31 \$294.72		294.72	
Maintenance Expense : Manure Thickening Spare Parts	1	8 TBM Reduction Gearbox 150 200-100717 <b>3</b> \$6,758.14 -\$2,027.44 \$4,730.70		4,730.70	

**Total** \$7,192.00