



Nutrient Control Systems
130 Industrial Drive
Chambersburg, PA 17201
717-261-5711
www.ncsysinc.com

PREPARED FOR	DATE	IDENTIFIER	TAX	QUOTE #19
Marks Farm	07/01/2022		0%	Parts for rebuild of ETO 7.5 pump
DESCRIPTION				
ETO 7.5 Pump rebuild parts				

NO.	DESCRIPTION	QTY.	PRICE	EXT. PRICE
1	Gasket ETO-100	2	\$23.99	\$47.98
2	Bearing	1	\$382.36	\$382.36
3	7.5 impeller	1	\$828.37	\$828.37
4	Mechanical Seal-100 Series	1	\$143.14	\$143.14
5	Bearing	1	\$154.71	\$154.71
6	O-Ring (568-253)	1	\$3.05	\$3.05
7	Mechanical Seal-100 Series	1	\$473.07	\$473.07
8	O-Ring (568-266)	1	\$5.42	\$5.42
9	O-Ring	1	\$5.51	\$5.51
10	Lip Seal	1	\$4.79	\$4.79
11	O-Ring	1	\$0.70	\$0.70
SUBTOTAL				\$2,049.10
SALES TAX				\$0.00
TOTAL				\$2,049.10

QUOTE IS VALID FOR 10 DAYS. Shipping charges are additional & will be added at invoicing.