

933573

8.00 - 10.15 + 11.45 - 12.30 - 3

10-13 9.00 - 9.30 - .5

QTY	P/N	DESCRIPTION	EA	TOTAL
1	SC			20.00
1		rewind		925.00
* 1	1.00906 (52)	screw		
* 1	0.05551 (52)	spiral conveyor		
* 1	1.00520 (8)	mech. seal		
* 1	1.00521 (12)	mech. seal		
* 1	1.00204 (15)	bearing		
* 1	1.00304 (38)	OR ring		
* 1	1.00203 (40)	bearing		
* 1	1.00300 (44)	OR ring		
* 1	1.00305 (46)	OR ring		
* 2	0.00244 (4)	support blade		
* 4	1.00164 (2)	screws		
* 4	1.00464 (3)	washers		
2	70.00-2+	trans. oil	7.64	15.28
				960.28
		SC	3.5	362.50
		CC+L	5	375.00
		failed hypot + surge test - motor is wet		1597.78
		inside - pump parts were rusty		
		and hard to get apart - steamed		
		and baked windings - failed		
		hypot and surge tests - needs		
		rewound		

PO# North Florida Hbl.

PTS5.5

- Need approval to proceed
- Needs rewind
- Need parts

NCS Equipment Repair Information Sheet

Customer Name NFI - Stock
Receipt/Drop Off Date 10/4 / 1
Model and Serial# PTS 5.5 KW 100 - 14M00856CR
KW/HP 5.5 KW / 7.5 HP
Site Voltage ~~480~~
Customer Complaint _____
Service Requested Rewind
Voltage Requested 230/460
Repair Shop Name S+S
Repair Shop Job/Tag Number 933573
Doris Ticket Number/PO# _____

Quantity Repair Shop Parts Request

1. ① 1.00906 (57) screw
2. ① 0.02551 (52) spiral conveyor
3. ① 1.00520 (8) mechanical seal
4. ① 1.00521 (12) mechanical seal
5. ① 1.00204 (15) bearing
6. ① 1.00304 (39) oring
7. ① 1.00203 (40) bearing
8. ① 1.00300 (44) oring
9. ① 1.00305 (46) oring
10. ② 0.00244 (4) support blade
12. ④ 1.00164 (2) screw
13. ④ 1.00464 (3) washer

- Needs rewind
- To repair \$1640.28

- 14.
- 15.
- 16.

Employee Requesting Service Patricia Toas Date 10/4/21