



SWECO, A Business Unit of M-I LLC
8029 Dixie Highway
Florence, KY 41042

INSTRUCTIONS FOR RETURN OF MOTORS FOR REPAIR/WARRANTY EVALUATION

DATE: 05/09/23

RMA# 453520

REMOVE ALL WEIGHTS BEFORE SENDING MOTOR

Please return your motor for Warranty/Repair Evaluation to:

ELECTRIC MOTOR TECHNOLOGIES

RMA 453520

5217 BEECH STREET

CINCINNATI, OH 45217

Please mark the RMA (Returned Material Authorization) number on the packaging and the bill of lading.

- 1. NOTE THAT ALL FREIGHT SHOULD BE PREPAID BY THE SHIPPER UNLESS SPECIAL APPROVAL IS RECEIVED. THE ABOVE ADDRESS WILL ****NOT**** ACCEPT COLLECT SHIPMENTS.**
- 2. Motors returned without a tag will NOT be evaluated for repair or warranty; these motors can only be used for MOTOR EXCHANGE credit to be used towards the purchase of a new motor.**
- 3. Motors returned during the warranty period will be evaluated for the cause of failure; the approval/denial notification will be sent via email.**
- 4. Remove all weights from the motor before sending for evaluation. We will not be responsible for any weights lost or damaged that are sent with the motor.**



SWECO, A Business Unit of M-I LLC
8029 Dixie Highway
Florence, KY 41042

See Page 2

Motor Part Number: Serial# E02C48051N-SH

Customer Name: Nutrient control systems

RMA Number: 453520

(please contact Customer Service Rep if RMA number has not been communicated)

Reason for Return: Over amp at start up

Details of Issue/Failure:

Motor was hard to turn. Would over
amp at start up.

This form needs to be completed & placed inside the crate of each motor sent for evaluation and repair.

Once the motor is evaluated, we will contact you with the quote. Please respond within two weeks. Please verify the motor part number before shipping. Motors sent in parts will void the warranty. Motors sent without nameplates will not be evaluated and will be returned at your expense.