



RMA# LF7323

NCS Equipment Repair Information Sheet

Customer Name (MCR) Stauffer

Receipt/Drop Off Date 07/03/23

Model and Serial# PTS 18.5-150 P11982

KW/HP 18.5kw

Site Voltage ~~460V~~ 230-460V

Customer Complaint Cap plug missing causing failure

Service Requested evaluation

Voltage Requested ~~460~~ same as it was brought in

Repair Shop Name S&S

Repair Shop Job/Tag Number _____

Doris Ticket Number/PO# 1749 PO# 9115-LFW

Quantity

Repair Shop Parts Request

1. ① 1.00210 Bearing
2. ① 1.00590 Plug
3. ① 1.00282 Oring
4. ① 1.00211 Bearing
5. ① 1.00313 Oring
6. ① 1.00314 Oring

To repair \$2467.30
price includes rewind,
new oil, and labor.

- 7.
- 8.
- 9.
- 10.
- 11.
- 12.
- 13.
- 14.
- 15.

Requesting Employee _____ Date _____