



LF Bioenergy

LF Bioenergy LF1 LLC
2950 N. Hardwood St.
Suite 2200
Dallas TX 75201
Tax ID # 87-1230439

Vendor

Nutrient Control Systems Inc.
130 Industrial Drive
Chambersburg PA 17201
United States

Ship To

Stauffer OPEX
1080 County Route 55
North Lawrence NY 12967
United States

Purchase Order

Date 7/23/2024
PO # PO201
Receive By
Terms Net 30
Incoterm

Project

Memo

Parts

| Item | Quantity | Description | Rate | Amount | Tax Amt. |
|---|----------|--|------|----------|----------|
| Maintenance Expense : Manure Thickening Spare Parts | 1 | O-Ring - Inventory No. 200-100313 x 1 | | 4.47 | |
| Maintenance Expense : Manure Thickening Spare Parts | 1 | O-Ring - Inventory No. 200-100302 x 1 | | 0.56 | |
| Maintenance Expense : Manure Thickening Spare Parts | 1 | Lip Seal - Inventory No. 200-102125 x1 | | 19.22 | |
| Maintenance Expense : Manure Thickening Spare Parts | 1 | Lip Seal (old P/N 1.00350) - Inventory No. 200-100351 x 1 | | 66.34 | |
| Maintenance Expense : Manure Thickening Spare Parts | 1 | Green Gasket / O-Ring ETO-150 - Inventory No. 200-001806 x1 | | 9.87 | |
| Maintenance Expense : Manure Thickening Spare Parts | 1 | mechanical Seal-150 Series - Inventory No. 200-100522 x1 | | 583.01 | |
| Maintenance Expense : Manure Thickening Spare Parts | 1 | TBM Reduction Gearbox 150 - Inventory No. 200-100717 x1 | | 1,576.90 | |
| Maintenance Expense : Manure Thickening Spare Parts | 1 | TBM 150 Mixer Bushing with Ceramic Coating - Inventory No. 200-007730 x1 | | 316.37 | |

Total \$2,576.74