



LF Bioenergy

LF Bioenergy LF1 LLC  
2950 N. Hardwood St.  
Suite 2200  
Dallas TX 75201  
Tax ID # 87-1230439

**Vendor**

Nutrient Control Systems Inc.  
130 Industrial Drive  
Chambersburg PA 17201  
United States

**Ship To**

Stauffer  
1080 County Route 55  
North Lawrence NY 12967  
United States

# Purchase Order

**Date** 11/6/2024  
**PO #** PO289  
**Receive By**  
**Terms** Net 30  
**Incoterm**

**Project**

**Memo**

Quote #376 TBM 150'S PM rebuild kit

Item	Quantity	Description	Rate	Amount	Tax Amt.
Maintenance Expense : Manure Thickening Spare Parts	1	1 O-Ring TBM 100 200-100282 <b>10</b> \$55.92 -\$16.77 \$39.14		39.14	
Maintenance Expense : Manure Thickening Spare Parts	1	2 O-Ring 200-100313 <b>10</b> \$63.87 -\$19.16 \$44.71		44.71	
Maintenance Expense : Manure Thickening Spare Parts	1	3 Green Gasket 200-001806 <b>10</b> \$140.98 -\$42.29 \$98.69		98.69	
Maintenance Expense : Manure Thickening Spare Parts	1	4 Lip Seal 200-100351 <b>10</b> \$274.54 -\$82.36 \$192.18		192.18	
Maintenance Expense : Manure Thickening Spare Parts	1	5 Lip Seal 200-102125 <b>20</b> \$947.64 -\$284.29 \$663.35		663.35	
Maintenance Expense : Manure Thickening Spare Parts	1	6 mechanical Seal-150 Series 200-100522 <b>10</b> \$8,328.69 -\$2,498.61 \$5,830.08		5,830.08	

**Total** \$6,868.15