



LF Bioenergy

LF Bioenergy LF1 LLC
2950 N. Hardwood St.
Suite 2200
Dallas TX 75201
Tax ID # 87-1230439

Vendor
Nutrient Control Systems Inc.
130 Industrial Drive
Chambersburg PA 17201
United States

Ship To
Stauffer
1080 County Route 55
North Lawrence NY 12967
United States

Purchase Order

Date 11/6/2024
PO # PO286
Receive By
Terms Net 30
Incoterm

Project

Memo

Quote #394 Cable Replacement (4 units)

Item	Quantity	Description	Rate	Amount	Tax Amt.
Maintenance Expense : Manure Thickening Spare Parts	1	1 Cable Tie 150 series 200-101474 4 \$29.57 -\$8.87 \$20.70		20.70	
Maintenance Expense : Manure Thickening Spare Parts	1	2 Cable Gland Seal 200-002638 4 \$35.30 -\$10.59 \$24.71		24.71	
Maintenance Expense : Manure Thickening Spare Parts	1	3 Cable Gland PTS/TBM 150 200-002639 4 \$252.28 -\$75.68 \$176.60		176.60	
Maintenance Expense : Manure Thickening Spare Parts	1	4 Sheath Old Number 1.01810 200-202574 4 \$53.86 -\$16.16 \$37.70		37.70	
Maintenance Expense : Manure Thickening Spare Parts	1	5 Cable Gland Gasket 150 series 200-001269 4 \$24.17 -\$7.25 \$16.92		16.92	
Maintenance Expense : Manure Thickening Spare Parts	1	6 Cable 150 series 200-101598 100 \$4,608.35 -\$1,382.51 \$3,225.85		3,225.85	

Total \$3,502.48