



LF Bioenergy

LF Bioenergy LF1 LLC
2950 N. Hardwood St.
Suite 2200
Dallas TX 75201
Tax ID # 87-1230439

Vendor
Nutrient Control Systems Inc.
130 Industrial Drive
Chambersburg PA 17201
United States

Ship To
LF Bioenergy LF1
1080 County Route 55
North Lawrence NY 12967
United States

Purchase Order

Date 6/4/2025
PO # PO498
Receive By
Terms Net 30
Incoterm

Project

Memo

Browns BDS Replaced all bearing, Sand blasted, cleaned bolt threads, replaced oil, and cleaned motor and tested. NO.

Item	Quantity	Description	Rate	Amount	Tax Amt.
Maintenance Expense : Manure Thickening Spare Parts	1	O-Ring 200-100282OPEXManure Thickening1 \$3.91 \$3.91		3.91	
Maintenance Expense : Manure Thickening Spare Parts	1	O-Ring 200-100314OPEXManure Thickening1 \$4.40 \$4.40		4.40	
Maintenance Expense : Manure Thickening Spare Parts	1	O-Ring 200-100313OPEXManure Thickening1 \$4.47 \$4.47		4.47	
Maintenance Expense : Manure Thickening Spare Parts	1	PTS-150/200 cutting Blade 200-000630 OPEXManure Thickening2 \$46.58 \$93.16		93.16	
Maintenance Expense : Manure Thickening Spare Parts	1	18.5 kW Impeller 200-001034OPEX Manure Thickening1 \$678.63 \$678.63		678.63	
Maintenance Expense : Manure Thickening Spare Parts	1	Mechanical Seal 150-Series 200-100525OPEXManure Thickening1 \$360.26 \$360.26		360.26	
Maintenance Expense : Manure Thickening Spare Parts	1	Brown BDSOPEXManure Thickening1 \$3,408.94 \$3,408.94		3,408.94	

Total \$4,553.77