



LF Bioenergy

LF Bioenergy LF1 LLC
2950 N. Hardwood St.
Suite 2200
Dallas TX 75201
Tax ID # 87-1230439

Vendor
Nutrient Control Systems Inc.
130 Industrial Drive
Chambersburg PA 17201
United States

Ship To
LF Bioenergy LF1
1080 County Route 55
North Lawrence NY 12967
United States

Purchase Order

Date 6/4/2025
PO # PO499
Receive By
Terms Net 30
Incoterm

Project

Memo

Inspected motor and tested good, replaced all chopping components as well as seals.

Item	Quantity	Description	Rate	Amount	Tax Amt.
Maintenance Expense : Manure Thickening Spare Parts	1	Sheath Old Number 1.01810 200-202574OPEXManure Thickening1 \$9.50 \$9.50		9.50	
Maintenance Expense : Manure Thickening Spare Parts	1	O-Ring 200-100314OPEXManure Thickening1 \$4.40 \$4.40		4.40	
Maintenance Expense : Manure Thickening Spare Parts	1	O-Ring 200-100313OPEXManure Thickening1 \$4.47 \$4.47		4.47	
Maintenance Expense : Manure Thickening Labor	1	LaborOPEXManure Thickening4 \$85.00 \$340.00		340.00	
Maintenance Expense : Manure Thickening Spare Parts	1	Cable 150 series 200-101598OPEX Manure Thickening20 \$32.26 \$645.17		645.17	
Maintenance Expense : Manure Thickening Spare Parts	1	Suction Support 150 series 200-002411 OPEXManure Thickening1 \$535.02 \$535.02		535.02	
Maintenance Expense : Manure Thickening Spare Parts	1	Spiral Conveyor PTS 150 200-011368 OPEXManure Thickening1 \$268.23 \$268.23		268.23	
Maintenance Expense : Manure Thickening Spare Parts	1	Mechanical Seal 200-100526OPEX Manure Thickening1 \$322.40 \$322.40		322.40	
Maintenance Expense : Manure Thickening Spare Parts	1	Mechanical Seal 150 Series 200-100525OPEXManure Thickening1 \$430.86 \$430.86		430.86	

Total \$2,560.05