



LF Bioenergy

LF Bioenergy LF3 LLC
2950 N. Harwood St
Ste 2200
Dallas TX 75201 EIN: 92-0410687
Tax ID # 92-0410687

Vendor

Nutrient Control Systems Inc.
130 Industrial Drive
Chambersburg PA 17201
United States

Ship To

LF03_Noble Hub
7662 NY-83
South Dayton NY 14138
United States

Purchase Order

Date 9/2/2025
PO # PO615
Receive By
Terms Net 30
Incoterm

Project

Memo

Mixer M13287

Item	Quantity	Description	Rate	Amount	Tax Amt.
Maintenance Expense : Manure Thickening Maintenance Expense : Manure Thickening Maintenance Labor	1	LaborOPEXManure Thickening1255.00 \$255.00		255.00	
Maintenance Expense : Manure Thickening Maintenance Expense : Manure Thickening Spare Parts	1	O-ringOPEXManure Thickening1 \$4.47 \$4.47 200-100313		4.47	
Maintenance Expense : Manure Thickening Maintenance Expense : Manure Thickening Spare Parts	1	Lip SealOPEXManure Thickening1 \$19.22 \$19.22 200-100351		19.22	
Maintenance Expense : Manure Thickening Maintenance Expense : Manure Thickening Spare Parts	1	Lip sealOPEXManure Thickening2 \$33.16 \$66.33 300-102125		66.33	
Maintenance Expense : Manure Thickening Maintenance Expense : Manure Thickening Spare Parts	1	HO-3 ISO VG-150 HD lube oilOPEX Manure Thickening1 \$36.84 \$36.84 L0764-057L		36.84	
Maintenance Expense : Manure Thickening Maintenance Expense : Manure Thickening Spare Parts	1	BearingOPEXManure Thickening1 \$145.36 \$145.36 200-100212		145.36	
Maintenance Expense : Manure Thickening Maintenance Expense : Manure Thickening Spare Parts	1	Mechanical Seal 150 SeriesOPEX Manure Thickening1 \$521.29 \$521.29 200-100522		521.29	
Maintenance Expense : Manure Thickening Maintenance Expense : Manure Thickening Spare Parts	1	Motor Casing w/ Stator TBM 15/PTS150 4POPEXManure Thickening 1 \$2,311.89 \$2,311.89 200-000654		2,311.89	

Total \$3,360.40