



LF Bioenergy

LF Bioenergy LF3 LLC  
2950 N. Harwood St  
Ste 2200  
Dallas TX 75201 EIN: 92-0410687  
Tax ID # 92-0410687

**Vendor**

Nutrient Control Systems Inc.  
130 Industrial Drive  
Chambersburg PA 17201  
United States

**Ship To**

LF03\_Noble Hub  
7662 NY-83  
South Dayton NY 14138  
United States

# Purchase Order

**Date** 9/2/2025  
**PO #** PO614  
**Receive By**  
**Terms** Net 30  
**Incoterm**

**Project**

**Memo**

Mixer M13280

| Item  | Quantity | Description   | Rate | Amount   | Tax Amt. |
|---|----------|---|------|----------|----------|
| Maintenance Expense : Manure Thickening<br>Maintenance Expense : Manure Thickening<br>Maintenance Labor | 1        | LaborOPEXManure Thickening1255.00<br>\$255.00   |      | 255.00   |          |
| Maintenance Expense : Manure Thickening<br>Maintenance Expense : Manure Thickening<br>Spare Parts       | 1        | O-ringOPEXManure Thickening1 \$4.47<br>\$4.47 200-100313  |      | 4.47     |          |
| Maintenance Expense : Manure Thickening<br>Maintenance Expense : Manure Thickening<br>Spare Parts       | 1        | Lip SealOPEXManure Thickening1<br>\$19.22 \$19.22 200-100351  |      | 19.22    |          |
| Maintenance Expense : Manure Thickening<br>Maintenance Expense : Manure Thickening<br>Spare Parts       | 1        | Lip sealOPEXManure Thickening2<br>\$33.16 \$66.33 300-102125  |      | 66.33    |          |
| Maintenance Expense : Manure Thickening<br>Maintenance Expense : Manure Thickening<br>Spare Parts       | 1        | HO-3 ISO VG-150 HD lube oilOPEX<br>Manure Thickening1 \$36.84 \$36.84<br>L0764-057L                   |      | 36.84    |          |
| Maintenance Expense : Manure Thickening<br>Maintenance Expense : Manure Thickening<br>Spare Parts       | 1        | BearingOPEXManure Thickening1<br>\$145.36 \$145.36 200-100212   |      | 145.36   |          |
| Maintenance Expense : Manure Thickening<br>Maintenance Expense : Manure Thickening<br>Spare Parts       | 1        | Mechanical Seal 150 SeriesOPEX<br>Manure Thickening1 \$521.29 \$521.29<br>200-100522                  |      | 521.29   |          |
| Maintenance Expense : Manure Thickening<br>Maintenance Expense : Manure Thickening<br>Spare Parts       | 1        | Motor Casing w/ Stator TBM<br>15/PTS150 4POPEXManure Thickening<br>1 \$2,311.89 \$2,311.89 200-000654 |      | 2,311.89 |          |

**Total** \$3,360.40