



LF Bioenergy

LF Bioenergy LF3 LLC
2950 N. Harwood St
Ste 2200
Dallas TX 75201 EIN: 92-0410687
Tax ID # 92-0410687

Vendor

Nutrient Control Systems Inc.
130 Industrial Drive
Chambersburg PA 17201
United States

Ship To

LF03_Noble Hub
7662 NY-83
South Dayton NY 14138
United States

Purchase Order

Date 12/31/2025
PO # PO783
Receive By
Terms Net 30
Incoterm

Project

Memo

Spare Cord Repair

Item	Quantity	Description	Rate	Amount	Gross Amt	Tax Amt.
Maintenance Expense : Manure Thickening Maintenance Expense : Manure Thickening Spare Parts	1	Eyelet TerminalManure ThickeningOPEX Maintenance63100 - Manure Thickening Maintenance Expense7 \$5.73 \$5.73		5.73	5.73	
Maintenance Expense : Manure Thickening Maintenance Expense : Manure Thickening Spare Parts	1	Plug for Dual Corded MixersManure ThickeningOPEXMaintenance63100 - Manure Thickening Maintenance Expense1 \$70.86 \$70.86		70.86	70.86	
Maintenance Expense : Manure Thickening Maintenance Expense : Manure Thickening Spare Parts	1	O-Ring TBM 100 (568-265)Manure ThickeningOPEXMaintenance63100 - Manure Thickening Maintenance Expense1 \$3.91 \$3.91		3.91	3.91	
Maintenance Expense : Manure Thickening Maintenance Expense : Manure Thickening Spare Parts	1	Cable 150 SeriesManure Thickening OPEXMaintenance63100 - Manure Thickening Maintenance Expense1 \$645.17 \$645.17		645.17	645.17	

Total \$725.67