



Purchase Order

LF BioEnergy

Date 6/29/2023
PO # PO33
Receive By
Terms Net 30
Incoterm

LF Bioenergy LF1 LLC
2950 N. Hardwood St.
Suite 2200
Dallas TX 75201
Tax ID # 87-1230439

Vendor

Nutrient Control Systems Inc.
130 Industrial Drive
Chambersburg PA 17201
United States

Ship To

LF1-STAU-FID
1080 County Route 55
North Lawrence NY 12967
United States

Project

Memo

Spare Parts for Manure Separator

Item	Quantity	Description	Rate	Amount	Tax Amt.
63103 : MRO: Manure Thickening Spare Parts	4	Gasket for Flange	59.78	239.12	
63103 : MRO: Manure Thickening Spare Parts	10	Gasket for Clamp on Feeder Assembly	4.97	49.70	
63103 : MRO: Manure Thickening Spare Parts	4	Stainless Steel Clamp For Feeder Assembly	41.66	166.64	
63103 : MRO: Manure Thickening Spare Parts	10	Brass Nut for Ban Clamp	11.93	119.30	
63103 : MRO: Manure Thickening Spare Parts	3	Ban Clamps Classic 48"	655.88	1,967.64	

Total \$2,542.40