



Purchase Order

LF Bioenergy LF1 LLC
2950 N. Hardwood St.
Suite 2200
Dallas TX 75201
Tax ID # 87-1230439

Date 8/9/2024
PO # PO213
Receive By
Terms Net 30
Incoterm

Vendor

Nutrient Control Systems Inc.
130 Industrial Drive
Chambersburg PA 17201
United States

Ship To

LF1-STAU-FID
1080 County Route 55
North Lawrence NY 12967
United States

Project

Memo

QUOTE #335

Item	Quantity	Description	Rate	Amount	Tax Amt.
Maintenance Expense : Manure Thickening	1	Labor 4.00 \$85.00 \$340.00		340.00	
Maintenance Expense : Manure Thickening					
Maintenance Labor					
Maintenance Expense : Manure Thickening	1	HO-3 ISO VG-150 HD lube oil: Sold by		36.84	
Maintenance Expense : Manure Thickening		the liter for planetary L0764-057L 1			
Other Maintenance Expense		\$36.84 \$36.84			
Maintenance Expense : Manure Thickening	1	Lip Seal 200-100351 1 \$19.22 \$19.22		19.22	
Maintenance Expense : Manure Thickening					
Other Maintenance Expense					
Maintenance Expense : Manure Thickening	1	Lip Seal (old P/N 1.00350) 200-102125		66.34	
Maintenance Expense : Manure Thickening		2 \$33.17 \$66.34			
Other Maintenance Expense					
Maintenance Expense : Manure Thickening	1	TBM 150 Mixer Bushing with Ceramic		316.37	
Maintenance Expense : Manure Thickening		Coating 200-007730 1 \$316.37 \$316.37			
Other Maintenance Expense					
Maintenance Expense : Manure Thickening	1	Green Gasket / O-Ring ETO-150		9.87	
Maintenance Expense : Manure Thickening		200-001806 1 \$9.87 \$9.87			
Other Maintenance Expense					
Maintenance Expense : Manure Thickening	1	O-Ring 200-100313 1 \$4.47 \$4.47		4.47	
Maintenance Expense : Manure Thickening					
Other Maintenance Expense					
Maintenance Expense : Manure Thickening	1	mechanical Seal-150 Series		583.01	
Maintenance Expense : Manure Thickening		200-100522 1 \$583.01 \$583.01			
Other Maintenance Expense					
Maintenance Expense : Manure Thickening	1	TBM Reduction Gearbox 150		1,576.90	
Maintenance Expense : Manure Thickening		200-100717 1 \$1,576.90 \$1,576.90			
Other Maintenance Expense					
Maintenance Expense : Manure Thickening	1	Motor Casing TBM/PTS 15KW 230/460		2,311.89	
Maintenance Expense : Manure Thickening		200-006490 1 \$2,311.89 \$2,311.89			
Other Maintenance Expense					

Total \$5,264.91