



LF Bioenergy

LF Bioenergy LF1 LLC
2950 N. Hardwood St.
Suite 2200
Dallas TX 75201
Tax ID # 87-1230439

Vendor
Nutrient Control Systems Inc.
130 Industrial Drive
Chambersburg PA 17201
United States

Ship To
Stauffer
1080 County Route 55
North Lawrence NY 12967
United States

Purchase Order

Date 1/17/2025
PO # PO342
Receive By
Terms Net 30
Incoterm

Project

Memo

Spare Parts

Item	Quantity	Description	Rate	Amount	Tax Amt.
Maintenance Expense : Manure Thickening Spare Parts	1	BearingOPEXManure Thickening1 \$155.24 \$155.24 Inventory No. 200-100211		155.24	
Maintenance Expense : Manure Thickening Spare Parts	1	BearingOPEXManure Thickening1 \$145.36 \$145.36 Inventory No. 200-100212		145.36	
Maintenance Expense : Manure Thickening Spare Parts	1	Mechanical Seal-150 SeriesOPEX Manure Thickening4 \$521.29 \$2,085.17 Inventory No. 200-100522		2,085.17	
Maintenance Expense : Manure Thickening Spare Parts	1	TBM Reduction Gearbox 150OPEX Manure Thickening4 \$1,576.90 \$6,307.59 Inventory No. 200-100717		6,307.59	

Total \$8,693.36