



LF Bioenergy

LF Bioenergy LF1 LLC
2950 N. Hardwood St.
Suite 2200
Dallas TX 75201
Tax ID # 87-1230439

Vendor

Nutrient Control Systems Inc.
130 Industrial Drive
Chambersburg PA 17201
United States

Ship To

Stauffer
1080 County Route 55
North Lawrence NY 12967
United States

Purchase Order

Date 11/6/2024
PO # PO290
Receive By
Terms Net 30
Incoterm

Project

Memo

Quote #401 PTS 150's pm Rebuild

Item	Quantity	Description	Rate	Amount	Tax Amt.
Maintenance Expense : Manure Thickening Spare Parts	1	1 Oil for cri-man pumps 1 gal Lubriplate iso 32 200-L0116- 007 5 \$683.44 -\$205.03 \$478.40		478.40	
Maintenance Expense : Manure Thickening Spare Parts	1	2 O-Ring 200-100282 4 \$22.37 -\$6.71 \$15.66		15.66	
Maintenance Expense : Manure Thickening Spare Parts	1	3 O-Ring 200-100314 4 \$25.12 -\$7.54 \$17.59		17.59	
Maintenance Expense : Manure Thickening Spare Parts	1	4 O-Ring 200-100313 4 \$25.55 -\$7.66 \$17.88		17.88	
Maintenance Expense : Manure Thickening Spare Parts	1	5 Mechanical Seal 200-100526 4 \$1,842.28 -\$552.68 \$1,289.60		1,289.60	
Maintenance Expense : Manure Thickening Spare Parts	1	6 Mechanical Seal 200-100525 4 \$2,058.63 -\$617.59 \$1,441.04		1,441.04	

Total \$3,260.17