



LF Bioenergy

LF Bioenergy LF1 LLC
2950 N. Hardwood St.
Suite 2200
Dallas TX 75201
Tax ID # 87-1230439

Purchase Order

Date 11/6/2024
PO # PO287
Receive By
Terms Net 30
Incoterm

Vendor
Nutrient Control Systems Inc.
130 Industrial Drive
Chambersburg PA 17201
United States

Ship To
Stauffer
1080 County Route 55
North Lawrence NY 12967
United States

Project

Memo

Quote #377 PTS 150'S Cutting Rebuild Kit

Item	Quantity	Description	Rate	Amount	Tax Amt.
Maintenance Expense : Manure Thickening Spare Parts	1	1 Screw PTS 150 200-100154 18 \$52.95 -\$15.88 \$37.06		37.06	
Maintenance Expense : Manure Thickening Spare Parts	1	2 Spiral Conveyor PTS-150 200-011368 3 \$1,149.57 -\$344.87 \$804.70		804.70	
Maintenance Expense : Manure Thickening Spare Parts	1	3 PTS-150/200 cutting Blade 200-000630 6 \$399.25 -\$119.77 \$279.47		279.47	
Maintenance Expense : Manure Thickening Spare Parts	1	4 PTS-150/200 Cutting Blade Support 200-000629 6 \$626.30 -\$187.89 \$438.41		438.41	
Maintenance Expense : Manure Thickening Spare Parts	1	5 15Kw Impeller 200-001035 2 \$2,221.02 -\$666.31 \$1,554.71		1,554.71	
Maintenance Expense : Manure Thickening Spare Parts	1	6 18.5 kW Impeller 200-001034 2 \$1,938.95 -\$581.69 \$1,357.27		1,357.27	
Maintenance Expense : Manure Thickening Spare Parts	1	7 PTS 150 Bearing Support 200-000640 2 \$869.47 -\$260.84 \$608.63		608.63	
Maintenance Expense : Manure Thickening Spare Parts	1	8 Motor Support 150 Series 200-000642 2 \$2,650.00 -\$795.00 \$1,855.00		1,855.00	

Total \$6,935.25