



LF Bioenergy

LF Bioenergy LF1 LLC
2950 N. Hardwood St.
Suite 2200
Dallas TX 75201
Tax ID # 87-1230439

Vendor

Nutrient Control Systems Inc.
130 Industrial Drive
Chambersburg PA 17201
United States

Ship To

LF1-STAU-FID
1080 County Route 55
North Lawrence NY 12967
United States

Purchase Order

Date 2/21/2025
PO # PO377
Receive By
Terms Net 30
Incoterm

Project

Memo

Digester Mixer Repair

Item	Quantity	Description	Rate	Amount	Tax Amt.
Maintenance Expense : Digester Maintenance Labor	1	Tech		2,550.00	
Maintenance Expense : Digester Maintenance Labor	1	Lead Tech		3,600.00	
Maintenance Expense : Digester Maintenance Labor	1	Tech Per Diem		600.00	
Maintenance Expense : Digester Maintenance Labor	1	Lead Tech Per Diem		600.00	
Maintenance Expense : Digester Maintenance Labor	1	Travel for Tech		520.00	
Maintenance Expense : Digester Maintenance Labor	1	Travel for Lead Tech		520.00	

Total \$8,390.00