

Nutrient Control Systems, Inc.
 130 Industrial Drive
 Chambersburg PA 17201
 717-261-5711



Invoice

Date	Invoice #
5/28/2025	13265

JoBo Holsteins LLC
 John Hess
 200 Tall Oak Rd.
 Gettysburg, PA 17325

Thank you! We appreciate your business.	Ticket#	P.O. No.	Terms	Project
	2373		Net 30	
Description	Qty	Rate	Amount	
Lead Electrician Service Hours	6	110.00	660.00	
Lead Electrician Travel	1	85.00	85.00	
<p>4/4/25: Cole reported communication issues. After several hours trouble shooting it was determined that I would have to make a trip to Jobo to determine the problem.</p> <p>4/5/25: I found the problem to be conflicting addressing somewhere on Jobos internet network the problem was so profound that it was interfering with the communications between the HMI and PLC. I corrected the problem by re-addressing my addresses on both the HMI and PLC.</p> <p>4/7/25: A call from Cole at Jobo. They installed a new HBC discharge conveyor and it needed timing adjustments for the conveyor proximity switch.</p>				

Please contact aconklin@ncsysinc.com or 717-261-5711 with any questions or concerns.	Total	\$745.00
	Payments/Credits	\$0.00
	Balance Due	\$745.00



www.NCSYSINC.com
www.NoBullSupply.com
www.NuFiberSoil.com

