



LF Bioenergy

LF Bioenergy LF3 LLC  
2950 N. Harwood St  
Ste 2200  
Dallas TX 75201 EIN: 92-0410687  
Tax ID # 92-0410687

**Vendor**  
Nutrient Control Systems Inc.  
130 Industrial Drive  
Chambersburg PA 17201  
United States

**Ship To**  
LF03\_Noble Hub  
7662 NY-83  
South Dayton NY 14138  
United States

# Purchase Order

**Date** 7/11/2025  
**PO #** PO543  
**Receive By**  
**Terms** Net 30  
**Incoterm**

**Project**

## Memo

Quote #519

Item	Quantity	Description	Rate	Amount	Tax Amt.
Maintenance Expense : Manure Thickening Maintenance Expense : Manure Thickening Maintenance Labor	1	LaborOPEXManure Thickening285.00 \$170.00		170.00	
Maintenance Expense : Manure Thickening Maintenance Expense : Manure Thickening Other Maintenance Expense	1	External Retaining RingOPEXManure Thickening1 \$1.21 \$1.21 200-100252		1.21	
Maintenance Expense : Manure Thickening Maintenance Expense : Manure Thickening Other Maintenance Expense	1	O-RingOPEXManure Thickening1 \$3.86 \$3.86 200-100300		3.86	
Maintenance Expense : Manure Thickening Maintenance Expense : Manure Thickening Other Maintenance Expense	1	Lip SealOPEXManure Thickening1 \$19.22 \$19.22 200-100351		19.22	
Maintenance Expense : Manure Thickening Maintenance Expense : Manure Thickening Other Maintenance Expense	1	Lip sealOPEXManure Thickening2 \$33.16 \$66.33 300-102125		66.33	
Maintenance Expense : Manure Thickening Maintenance Expense : Manure Thickening Other Maintenance Expense	1	HO-3 ISO VG-150 HD lube oilOPEX Manure Thickening1 \$67.00 \$67.00 L0764-057L		67.00	
Maintenance Expense : Manure Thickening Maintenance Expense : Manure Thickening Other Maintenance Expense	1	Mechanical SealOPEXManure Thickening1 \$244.06 \$244.06 200-100529		244.06	

**Total** \$571.68