



LF Bioenergy

LF Bioenergy LF1 LLC  
2950 N. Hardwood St.  
Suite 2200  
Dallas TX 75201  
Tax ID # 87-1230439

**Vendor**

Nutrient Control Systems Inc.  
130 Industrial Drive  
Chambersburg PA 17201  
United States

**Ship To**

LF01\_Stauffer Farm  
1080 County Route 55  
North Lawrence NY 12967  
United States

# Purchase Order

**Date** 7/24/2025  
**PO #** PO562  
**Receive By**  
**Terms** Net 30  
**Incoterm**

**Project**

**Memo**

Quote #524/525/526 Rebuilds

Item	Quantity	Description	Rate	Amount	Tax Amt.
Maintenance Expense : Manure Thickening Maintenance Expense : Manure Thickening Other Maintenance Expense	1	M10964OPEXManure Thickening1 \$125.75 \$125.75 Mixer rebuild		125.75	
Maintenance Expense : Manure Thickening Maintenance Expense : Manure Thickening Other Maintenance Expense	1	P10344OPEXManure Thickening1 \$1,875.73 \$1,875.73 Pump rebuild		1,875.73	
Maintenance Expense : Manure Thickening Maintenance Expense : Manure Thickening Other Maintenance Expense	1	P10345OPEXManure Thickening1 \$1,904.69 \$1,904.69 Pump rebuild		1,904.69	

**Total** \$3,906.17