



LF Bioenergy

LF Bioenergy LF1 LLC  
2950 N. Hardwood St.  
Suite 2200  
Dallas TX 75201  
Tax ID # 87-1230439

**Vendor**

Nutrient Control Systems Inc.  
130 Industrial Drive  
Chambersburg PA 17201  
United States

**Ship To**

LF01\_Stauffer Farm  
1080 County Route 55  
North Lawrence NY 12967  
United States

# Purchase Order

Page 1 of 2

**Date** 7/22/2025  
**PO #** PO557  
**Receive By**  
**Terms** Net 30  
**Incoterm**

**Memo**

Quote #508 TBM Repair Parts

Item	Quantity	Description	Rate	Amount	Tax Amt.
Maintenance Expense : Manure Thickening	1	Seal Old Number 1.01811OPEX		8.31	
Maintenance Expense : Manure Thickening		Manure Thickening4 \$2.08 \$8.31			
Other Maintenance Expense		200-202575			
Maintenance Expense : Manure Thickening	1	Cable Gland SealOPEXManure		24.71	
Maintenance Expense : Manure Thickening		Thickening4 \$6.18 \$24.71 200-002638			
Other Maintenance Expense					
Maintenance Expense : Manure Thickening	1	O-Ring TBM 150 (568-265)OPEX		15.66	
Maintenance Expense : Manure Thickening		Manure Thickening4 \$3.92 \$15.66			
Other Maintenance Expense		200-100282			
Maintenance Expense : Manure Thickening	1	Lip SealOPEXManure Thickening4		76.87	
Maintenance Expense : Manure Thickening		\$19.22 \$76.87 200-100351			
Other Maintenance Expense					
Maintenance Expense : Manure Thickening	1	Green Gasket / O-Ring ETO-150OPEX		39.47	
Maintenance Expense : Manure Thickening		Manure Thickening4 \$9.87 \$39.47			
Other Maintenance Expense		200-001806			
Maintenance Expense : Manure Thickening	1	O-Ring (568-169)OPEXManure		5.05	
Maintenance Expense : Manure Thickening		Thickening4 \$1.26 \$5.05 200-100306			
Other Maintenance Expense					
Maintenance Expense : Manure Thickening	1	O-RingOPEXManure Thickening4		4.48	
Maintenance Expense : Manure Thickening		\$1.12 \$4.48 200-100302			
Other Maintenance Expense					
Maintenance Expense : Manure Thickening	1	TBM 150 Mixer Bushing with Ceramic		1,102.91	
Maintenance Expense : Manure Thickening		CoatingOPEXManure Thickening4			
Other Maintenance Expense		\$275.73 \$1,102.91 200-007730			
Maintenance Expense : Manure Thickening	1	Mechanical Seal-150 SeriesOPEX		2,085.17	
Maintenance Expense : Manure Thickening		Manure Thickening4 \$521.29			
Other Maintenance Expense		\$2,085.17 200-100522			
Maintenance Expense : Manure Thickening	1	O-RingOPEXManure Thickening4		1.48	
Maintenance Expense : Manure Thickening		\$0.37 \$1.48 200-100301			
Other Maintenance Expense					
Maintenance Expense : Manure Thickening	1	WasherOPEXManure Thickening4		7.42	
Maintenance Expense : Manure Thickening		\$1.86 \$7.42 200-100461			
Other Maintenance Expense					
Maintenance Expense : Manure Thickening	1	Screw- TBM 100/150OPEXManure		17.51	
Maintenance Expense : Manure Thickening		Thickening4 \$4.38 \$17.51 200-100100			
Other Maintenance Expense					
Maintenance Expense : Manure Thickening	1	Screw TBM 100/150 OPEXManure		8.16	
Maintenance Expense : Manure Thickening		Thickening8 \$1.02 \$8.16 200-100390			
Other Maintenance Expense					
Maintenance Expense : Manure Thickening	1	Lip Seal (old P/N 1.00350)OPEX		265.34	
Maintenance Expense : Manure Thickening		Manure Thickening8 \$33.17 \$265.34			
Other Maintenance Expense		200-102125			
Maintenance Expense : Manure Thickening	1	Propeller TBM 15-150, old 0.00671		4,887.11	
Maintenance Expense : Manure Thickening		OPEXManure Thickening4 \$1,221.78			
Other Maintenance Expense		\$4,887.11 200-102125			
Maintenance Expense : Manure Thickening	1	TBM Reduction Gearbox 150OPEX		6,307.59	
Maintenance Expense : Manure Thickening		Manure Thickening4 \$1,576.90			
Other Maintenance Expense		\$6,307.59 200-100717			
Maintenance Expense : Manure Thickening	1	O-RingOPEXManure Thickening4		17.88	
Maintenance Expense : Manure Thickening		\$4.47 \$17.88 200-100313			
Other Maintenance Expense					
Maintenance Expense : Manure Thickening	1	Cable 150 series OPEXManure		2,580.68	
Maintenance Expense : Manure Thickening		Thickening80 \$32.26 \$2,580.68			
Other Maintenance Expense		200-101598			
Maintenance Expense : Manure Thickening	1	Crown Gear TBM-150 seriesOPEX		2,030.78	
Maintenance Expense : Manure Thickening		Manure Thickening4 \$507.70			



LF Bioenergy

# Purchase Order

Page 2 of 2

**Date**  
**PO #**

7/22/2025  
PO557

LF Bioenergy LF1 LLC  
2950 N. Hardwood St.  
Suite 2200  
Dallas TX 75201  
Tax ID # 87-1230439

Item	Quantity	Description	Rate	Amount	Tax Amt.
Other Maintenance Expense Maintenance Expense : Manure Thickening Maintenance Expense : Manure Thickening Other Maintenance Expense	1	\$2,030.78 200-001113 Cable Gland PTS/TBM 150OPEX Manure Thickening4 \$44.15 \$176.60 200-002639		176.60	

**Total** \$19,663.18