



LF Bioenergy

LF Bioenergy LF1 LLC  
2950 N. Hardwood St.  
Suite 2200  
Dallas TX 75201  
Tax ID # 87-1230439

**Vendor**

Nutrient Control Systems Inc.  
130 Industrial Drive  
Chambersburg PA 17201  
United States

**Ship To**

5202 Commerce Drive  
Lockport NY 14094  
United States

# Purchase Order

**Date** 8/18/2025  
**PO #** PO595  
**Receive By**  
**Terms** Net 30  
**Incoterm**

**Project**

**Memo**

PO for mixer parts

Item	Quantity	Description	Rate	Amount	Tax Amt.
Maintenance Expense : Manure Thickening Spare Parts	1	Lip SealOPEXManure Thickening1 \$19.22 \$19.22		19.22	
Maintenance Expense : Manure Thickening Spare Parts	1	(2) Lip sealOPEXManure Thickening1 \$66.33 \$66.33		66.33	
Maintenance Expense : Manure Thickening Spare Parts	1	(5) TBM 150 bushingsOPEXManure Thickening1 \$1,378.64 \$1,378.64		1,378.64	
Maintenance Expense : Manure Thickening Spare Parts	1	(4) mechanical seals TBMOPEX Manure Thickening1 \$2,085.17 \$2,085.17		2,085.17	
Maintenance Expense : Manure Thickening Spare Parts	1	(3) TBM reduction gearbox 150OPEX Manure Thickening1 \$4,730.70 \$4,730.70		4,730.70	

**Total** \$8,280.06