



LF Bioenergy

LF Bioenergy LF3 LLC
2950 N. Harwood St
Ste 2200
Dallas TX 75201 EIN: 92-0410687
Tax ID # 92-0410687

Vendor
Nutrient Control Systems Inc.
130 Industrial Drive
Chambersburg PA 17201
United States

Ship To
LF03_Noble Hub
7662 NY-83
South Dayton NY 14138
United States

Purchase Order

Date 8/14/2025
PO # PO589
Receive By
Terms Net 30
Incoterm

Project

Memo

4K mixer service

Item	Quantity	Description	Rate	Amount	Tax Amt.
Maintenance Expense : Manure Thickening	1	LaborOPEXManure Thickening1255.00		255.00	
Maintenance Expense : Manure Thickening		\$255.00			
Maintenance Labor					
Maintenance Expense : Manure Thickening	1	O-ringOPEXManure Thickening1 \$4.47		4.47	
Maintenance Expense : Manure Thickening		\$4.47 200-100313			
Spare Parts					
Maintenance Expense : Manure Thickening	1	Lip SealOPEXManure Thickening1		19.22	
Maintenance Expense : Manure Thickening		\$19.22 \$19.22 200-100351			
Spare Parts					
Maintenance Expense : Manure Thickening	1	Lip sealOPEXManure Thickening2		66.33	
Maintenance Expense : Manure Thickening		\$33.16 \$66.33 300-102125			
Spare Parts					
Maintenance Expense : Manure Thickening	1	HO-3 ISO VG-150 HD lube oilOPEX		36.84	
Maintenance Expense : Manure Thickening		Manure Thickening1 \$36.84 \$36.84			
Spare Parts		L0764-057L			
Maintenance Expense : Manure Thickening	1	BearingOPEXManure Thickening1		145.36	
Maintenance Expense : Manure Thickening		\$145.36 \$145.36 200-100212			
Spare Parts					
Maintenance Expense : Manure Thickening	1	Mechanical Seal 150 SeriesOPEX		521.29	
Maintenance Expense : Manure Thickening		Manure Thickening1 \$521.29 \$521.29			
Spare Parts		200-100522			
Maintenance Expense : Manure Thickening	1	Motor Casing w/ Stator TBM		2,311.89	
Maintenance Expense : Manure Thickening		15/PTS150 4POPEXManure Thickening			
Spare Parts		1 \$2,311.89 \$2,311.89 200-000654			

Total \$3,360.40