



LF Bioenergy

LF Bioenergy LF3 LLC
2950 N. Harwood St
Ste 2200
Dallas TX 75201 EIN: 92-0410687
Tax ID # 92-0410687

Vendor
Nutrient Control Systems Inc.
130 Industrial Drive
Chambersburg PA 17201
United States

Ship To
LF03_Noble Hub
7662 NY-83
South Dayton NY 14138
United States

Purchase Order

Date 10/13/2025
PO # PO677
Receive By
Terms Net 30
Incoterm

Project

Memo

P13126 5k

Item	Quantity	Description	Rate	Amount	Tax Amt.
Maintenance Expense : Manure Thickening Maintenance Expense : Manure Thickening Spare Parts	1	LaborManure ThickeningOPEX Maintenance3 \$120.00 \$360.00		360.00	
Maintenance Expense : Manure Thickening Maintenance Expense : Manure Thickening Spare Parts	1	Spiral Conveyor PTS 100 Series Manure ThickeningOPEXMaintenance1 \$232.06 \$232.06 200-002551		232.06	
Maintenance Expense : Manure Thickening Maintenance Expense : Manure Thickening Spare Parts	1	ISO 32 Oil by literManure Thickening OPEXMaintenance2 \$28.62 \$57.24 200-L0116-007L		57.24	
Maintenance Expense : Manure Thickening Maintenance Expense : Manure Thickening Spare Parts	1	O-ring (568-253)Manure Thickening OPEXMaintenance1 \$3.52 \$3.52 200-100305		3.52	
Maintenance Expense : Manure Thickening Maintenance Expense : Manure Thickening Spare Parts	1	O-ring Manure ThickeningOPEX Maintenance1 \$2.41 \$2.41 200-100304		2.41	
Maintenance Expense : Manure Thickening Maintenance Expense : Manure Thickening Spare Parts	1	O-ringManure ThickeningOPEX Maintenance1 \$4.14 \$4.14 200-100300		4.14	
Maintenance Expense : Manure Thickening Maintenance Expense : Manure Thickening Spare Parts	1	Impeller PTS 5.5-100 60HzManure ThickeningOPEXMaintenance1 \$549.88 \$549.88 200-002180		549.88	
Maintenance Expense : Manure Thickening Maintenance Expense : Manure Thickening Spare Parts	1	PTS 100 BladeManure Thickening OPEXMaintenance2 \$38.40 \$76.80 200-000243		76.80	
Maintenance Expense : Manure Thickening Maintenance Expense : Manure Thickening Spare Parts	1	Mechanical Seal-100 seriesManure ThickeningOPEXMaintenance1 \$107.22 \$107.22 200-100521		107.22	
Maintenance Expense : Manure Thickening Maintenance Expense : Manure Thickening Spare Parts	1	Mechanical Seal-100 seriesManure ThickeningOPEXMaintenance1 \$401.87 \$401.87 200-100520		401.87	

Total \$1,795.14