

# ORDER ACKNOWLEDGEMENT



Transply, Inc.  
 120 Pine Dr.  
 Greencastle, PA 17225  
 US  
 717-597-7828

[www.transply.com](http://www.transply.com)

Order Number	
1387784	
Order Date	Page
6/28/2023 07:43:23	1 of 1

**Bill To:**

Nutrient Control Systems  
 130 Industrial Dr  
 Chambersburg, PA 17201-3255  
 US

717-261-5711

**Ship To:**

Nutrient Control Systems  
 130 Industrial Dr  
 Chambersburg, PA 17201-3255  
 US

Ordered By: Brock Over

Customer ID: 105273

PO Number	Ship Via	Required Date	Taker	Terms
	Our Delivery	7/19/2023	JPARIS	1% 10, Net 30

Quantities		Item ID Item Description	Pricing UOM	Unit Price	Extended Price
Ordered	UOM				

1.00	EA	S	EVALUATION OR REPAIR	EA	543.18	543.18
------	----	---	----------------------	----	--------	--------

per the following:  
 Warranty Evaluation - Baldor EM3714T- Motor  
 was found to be over greased, water in endbell,  
 bearings rough.

\*This would not be a warranty.\*

Total Lines: 1

**SUB-TOTAL:** 543.18  
**TAX:** 0.00  
**AMOUNT TENDERED :** 0.00  
**AMOUNT DUE:** 543.18

U.S. Dollars

\*\*\*Prices are subject to change dependent upon manufacturers pricing policies and increase notifications. Tariffs may also be in effect until further notice.\*\*\*